

Date: Tuesday, 4/17/2007 11:12:22 AM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : AFT TUBE ASSEMBLY
Job Number : 31858	
Estimate Number : 10699	
P.O. Number : <u>N/A</u>	Part Number : D3391025
This Issue : 4/17/2007 S.O. No. : <u>N/A</u>	Drawing Number : D3391 REV F
Prsht Rev. : NC	Project Number : N/A
First Issue : <u>N/A</u> Type : LANDING GEAR	Drawing Revision : F
Previous Run : 31857	Material : <u>N/A</u>
Written By : <u>[Signature]</u>	Due Date : 5/20/2007 Qty: 1 Um: Each
Checked & Approved By : <u>[Signature]</u>	
Comment : Est Rev B 06-02-07 ECN773 dwg rev. D EC	
Est Rev: C 06-03-28 Update Manufacturing Instructions	
JLM	
est rev D 07.03.20 revF dwg ec	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D6014090	ALUMINUM EXTRUSION
-----	----------	--------------------



Comment: Qty.: 1.0000 f(s)/Unit Total : 1.0000 f(s)

ALUMINUM EXTRUSION

Pick:

Qty	Part Number	Description	Batch
-----	-------------	-------------	-------

1	D6014-090	Extrusion	<u>B26546</u>
---	-----------	-----------	---------------

Identify as D3391-3

[Signature] 07/04/23

2.0	MORI SEIKI	MORI SEIKI CNC LATHE LARGE
-----	------------	----------------------------



Comment: MORI SEIKI CNC LATHE LARGE

Turn as per Folio FA599

Rev: F & Dwg D3391 Rev: AA

[Signature] 07/04/23

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

[Signature] 07/04/23

4.0	HAAS1	HAAS CNC VERTICAL MACHINING #1
-----	-------	--------------------------------



Comment: HAAS

1-Machine as per Folio FA 599 Rev: AA & Dwg D3391 Rev: F

2-Deburr

[Signature] 07-06-10 (1)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 4/17/2007 11:12:22 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 31858

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

36 07-06-10 (1)

6.0

QC8

SECOND CHECK



Comment: SECOND CHECK

5.1 07/06/10

7.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Drill (PILOT HOLE) aft cap holes per Dwg D3391 using DT8803

DP 7-6-13

8.0

BENDING

BENDING MACHINE



Comment: NC Bender

Form as per Dwg D3391 Using Bend Prog 3391025

EL 7-6-14

9.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

DP 7-6-14

10.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Open Aft cap pilot hole to .208" as per Dwg D3391

2-Drill float bag holes using DT8809 as per Dwg D3391(Holes marked "A" Only.

3-Drill wearplate holes as per Dwg D3391 using DT8878(Mid Tube) & DT8217 Wearplate Jig.

*****Do Not Open To Finished Size*****

4-Drill Wearshoe holes as per DWG D3391 using DT8939 locating from 2 previously drilled aft wearplate holes.

5-Open up all wearshoe & wearplate and float bag holes to .257" + countersink as per Dwg D3391.

6-Deburr

BE 07-06-18

Tools: rill

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 4/17/2007 11:12:23 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 31858

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

11.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

2 Per 07/06/21

12.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

M-H 07/06/26

13.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

M 104144 BR/M-H 07-06-27

14.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

FL 07/07/17

15.0

D2646

Aft Cap



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Aft Cap

Pick:

Qty

Part Number

Description Batch

1

D2646

Aft Cap

B31335

16.0

D35371

WEARPAD



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

WEARPAD

B33287

17.0

D35377

Wearpad



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Wearpad

B31911

18.0

D35531

Gasket



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Gasket

B32740 FL 07/07/17

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 4/17/2007 11:12:23 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 31858

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description:

19.0

D35533

Gasket



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)
Gasket

BS2745.

20.0

AESS10KB366

INSERT



Comment: Qty.: 14.0000 Each(s)/Unit Total: 14.0000 Each(s)
Insert

Pick:

Qty Part Number Description Batch
14 AESS10KB366 Insert

m104192

21.0

AESS10KB316

INSERT



Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s)
INSERT

Pick:

Qty Part Number Description Batch
2 AESS10KB316 Insert
or NAS1330C3KB316

m17905

22.0

AESS10KB266

INSERT



Comment: Qty.: 6.0000 Each(s)/Unit Total: 6.0000 Each(s)
INSERT

Pick:

Qty Part Number Description Batch
2 AESS10KB266 Insert
or NAS1330C3KB266

~~m17905~~ m17905

23.0

NAS1330C3KB166

INSERT



Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s)
INSERT

Pick:

Qty Part Number Description Batch
8 NAS1330C3KB166 Insert

m102849

FL 07/07/17 ①

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 4/17/2007 11:12:23 AM

User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 31858

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

24.0

AN3C4A

BOLT



Comment: Qty.: 6.0000 Each(s)/Unit Total : 6.0000 Each(s)

Bolt

Pick:

Qty	Part Number	Description	Batch
2	AN3C4A	Bolt	m104537

25.0

AN3C5A

Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Bolt

m104118.

26.0

AN960C10L

washer



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)

Inventory

Pick:

Qty	Part Number	Description	Batch
2	AN960C10L	Washer	m104963.

27.0

NAS1515H3L

WASHER



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

WASHER

Pick:

Qty	Part Number	Description	Batch
2	NAS1515H3L	Washer	m104603.

28.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: SMALL & MEDIUM FAB RESOURCE 1

1-Install inserts as per Dwg D3391

2-Install Aft Cap as per Dwg D3391

A/R Sikaflex-241/-291

Sikaflex expiry date: 07/10

m104263

FD 07/07/17 (1)

29.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

En 07/07/17 (1)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: 12 Date: 09/10/13
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 4/17/2007 11:12:23 AM

User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 31858

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

30.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: _____

PPP

3 3525

Per 1/30

31.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Per 1/30

Job Completion



U Per 1/30

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART AEROSPACE LTD		Work Order: 31858
Description: Float Skidtube (412)		Part Number: D3391-3
Inspection Dwg: D3391	Rev: E F # 07.04.17	Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

☒ First Article ☐ Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
14.000	+/-0.010	14.00	✓			
3.500	+/-0.010	3.505	✓			
88.93	+/-0.030	88.93	✓			
44.995	+/-0.030	44.995	✓			
3.200	+/-0.010	3.199	✓			
1.526	+0.000/-0.030	1.526	✓			
0.200	+/-0.010	.200	✓			
7.500	+/-0.010	7.500	✓			
27.750	+/-0.010	27.750	✓			
31.750	+/-0.010	31.750	✓			
35.250	+/-0.010	35.250	✓			
0.400	+/-0.010	.400	✓			
Ø0.208	+0.005/-0.004					
3.300	+/-0.010	3.300	✓			
0.200	+/-0.010	.200	✓			
3.520	+/-0.010	3.520	✓			
0.687	+0.010/-0.000	.687	✓			
R0.062	+/-0.010	.062	✓			
Ø0.484	+0.005/-0.001	.486	✓			

Measured by: J.B. / BCF	Audited by: J.L.	Prototype Approval: N/A
Date: 07/04/23	Date: 07/06/10	Date: N/A

Rev	Date	Change	Revised by	Approved
A	06.04.24	New Issue P/O D3391-025	KJ/JLM	
B	06.06.19	Dwg revision update	KJ/JLM	



D3391-041/-043 FLOAT SKIDTUBE ASSEMBLY PARTS LIST

QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X	X	D3391-041	FLOAT SKIDTUBE ASSEMBLY
		D3391-043	FLOAT SKIDTUBE ASSEMBLY
1		D3391-011	FWD TUBE ASSEMBLY
1		D3391-013	MID TUBE ASSEMBLY
1		D3391-015	AFT TUBE ASSEMBLY
1	1	D3391-021	FWD TUBE ASSEMBLY
1	1	D3391-023	MID TUBE ASSEMBLY
1	1	D3391-025	AFT TUBE ASSEMBLY
1	1	D3564-1	WEARSHOE
1	1	D3564-3	WEARSHOE
1	1	D3564-5	WEARSHOE
2	2	D3566-1	GASKET
1	1	D3566-5	GASKET
24	24	AN3C4A	BOLT
12	12	AN3C6A	BOLT
8	8	AN3C7A	BOLT
44	44	AN960C10L	WASHER
4	4	MS27039C4-12	SCREW
4	4	NAS1515H4L	WASHER
4	4	AN960C416L	WASHER

GENERAL NOTES

- ALL DIMENSIONS ARE IN INCHES
- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4.1
POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3
- SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH AND AFTER INSTALLATION OF INSERTS. COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.
- USE DART DRILL TEMPLATE DTB217 TO LOCATE AND DRILL 'E' SIZE HOLES (#0.250-#0.257) FOR WEARSHOE INSERTS. C'SINK #0.391/#0.425 x 100' AS APPLICABLE AND INSTALL INSERTS EXCEPT WHERE INDICATED.

COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

F	07.01.18	ADD SS WEARSHOE, GASKET REMOVE FWD SADDLE HOLE -011/-021
E	06.04.25	CHANGE TOLERANCE, EASE MANUFACTURE
D	06.01.23	UPDATE TOLERANCE, CHANGE HOLE SIZE
C	05.09.27	LENGTHEN AFT EXTENSION
B	05.06.10	DRAWING UPDATES
A	05.02.07	NEW ISSUE
DESIGN	PH	DRAWN BY
CHECKED	PH	APPROVED
DATE	07.01.18	TITLE
		412 FLOAT SKIDTUBE
		REV. F
		SHEET 1 OF 5
		SCALE
		NTS


RELEASED
07.03.13 AH
FOR ECU #934

NO. 21858
WORK ORDER
SUBJECT TO AMENDMENT
CONTROLLED COPY
ENGINEERING
RETURN TO
SHOP COPY


RELEASED
 17.03.13 AH
 per ECN #934



D3391-011 ASSEMBLY AND BENDING DETAIL







D3391-021 ASSEMBLY AND BENDING DETAIL



D3566-13 GASKET

D3391-011/-021 WEARSHOE ASSEMBLY



D3564-13 WEARSHOE



D3391-011/-021 FWD TUBE ASSEMBLY PARTS LIST



QTY - 011	QTY - 021	PART NUMBER	DESCRIPTION
X	X	D3391-011	FWD TUBE ASSEMBLY
		D3391-021	FWD TUBE ASSEMBLY
1	1	D6013-047	FWD TUBE
1	1	D3401-041	TOW CAP
1	1	D3564-13	WEARSHOE
1	1	D3566-13	GASKET
10	10	AN3C4A	BOLT
4	4	NAS1515H3L	WASHER
10	10	AN960C10L	WASHER
30	20	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)

NO. 31858
 WORK ORDER
 RETURN TO
 ENGINEERING
 UNCONTROLLED COPY
 SUBJECT TO AMENDMENT
 WITHOUT NOTICE









D3391-1 DRILLING AND CUTTING DETAIL
 (MAKE FROM D6013-047 SKIDTUBE MATERIAL)

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.		DESIGN PH	DRAWN BY AH	DART DART AEROSPACE USA, INC. PORT HADLOCK, WA
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.		CHECKED [Signature]	APPROVED [Signature]	DRAWING NO. D3391
DATE 07.01.18		TITLE 412 FLOAT SKIDTUBE		REV. F SHEET 2 OF 5 SCALE 1:10



DRILL 'Q' (#0.332-#0.338)
INSTALL NAS1329S4KB140 INSERT
MS27039C4-08 SCREW
NAS1515H4L WASHER
AN960C416L WASHER
(TYP 4 PLACES)






D3391-013/-023 MID TUBE ASSEMBLY PARTS LIST

QTY - 013	QTY - 023	PART NUMBER	DESCRIPTION
X	X	D3391-013	MID TUBE ASSEMBLY
		D3391-023	MID TUBE ASSEMBLY
1	1	D2500-1-100	EXTRUSION
1	1	D3389-1	WEB
24	20	NAS1330S3KB116	INSERT (OR NAS1330C3KB116)
24	10	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)
4		NAS1329S4KB140	INSERT (OR NAS1329C3KB140)
4		NAS1515H3L	WASHER
4		AN960C10L	WASHER
4		NAS1515H4L	WASHER
4		AN960C416L	WASHER
4		MS27039C1-09	SCREW
4		MS27039C4-08	SCREW

D3391-013/-023 MID TUBE ASSEMBLY

- MATERIAL: MAKE FROM D2500-1-100 EXTRUSION
- INSTALL D3389-1 WEB TO OUTER TUBE USING SIKAFLEX-241/-291 PER QSI 015

NO. 31858
WORK ORDER
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE




COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.



DESIGN RH
CHECKED
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

DRAWN BY RH
APPROVED
DATE 07.01.18

DART DART AEROSPACE USA, INC.
PORT WOLCK, VA
DRAWING NO. D3391
TITLE 412 FLOAT SKIDTUBE
REV. F
SHEET 3 OF 5
SCALE 1:20




VIEW BB-BB
(SCALE 1:3)




DETAIL V
(SCALE 1:2)


D3391-3 AFT DRILLING AND CUTTING DETAIL
(MAKE FROM D6014-090 SKIDTUBE MATERIAL)




SECTION AA-AA
(SCALE 1:2)




SECTION N-N
(SCALE 1:2)




SECTION P-P
(SCALE 1:2)




SECTION Q-Q
(SCALE 1:2)



SECTION R-R
(SCALE 1:2)



DETAIL S
(SCALE 1:3)



VIEW W-W
(SCALE 1:3)


NO. 31858
WORK ORDER
SUBJECT TO ATTENDANT
WITHOUT NOTICE
ENGINEERING
RETURN TO
SHOP COPY

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL
AND IS SUPPLIED ON THE EXPRESS CONDITION
THAT IT IS NOT TO BE USED FOR ANY PURPOSE
OR COPIED OR COMMUNICATED TO ANY OTHER
PERSON WITHOUT WRITTEN PERMISSION FROM
DART AEROSPACE USA, INC.

DESIGN PH	DRAWN BY PH	DART DART AEROSPACE USA, INC. FORT HADLOCK, MA	REV. F
CHECKED H	APPROVED H	DRAWING NO. D3391	SHEET 4 OF 5
DATE 07.01.18	TITLE 412 FLOAT SKIDTUBE	SCALE 1:12	


RELEASED
07-03-13 PH
PER ECU #934




D3391-015 BENDING AND ASSEMBLY DETAIL



D3391-025 BENDING AND ASSEMBLY DETAIL



D3391-015 INSERT AND WEARPAD INSTALLATION DETAIL
(SEE TABLE)




D3391-025 INSERT AND WEARPAD INSTALLATION DETAIL
(SEE TABLE)

D3391-015/-025 AFT TUBE ASSEMBLY PARTS LIST

QTY - 015	QTY - 025	PART NUMBER	DESCRIPTION
X	X	D3391-015	AFT TUBE ASSEMBLY
		D3391-025	AFT TUBE ASSEMBLY
1	1	D6014-090	AFT TUBE
1	1	D2646	AFT CAP
1	1	D3537-1	WEARPAD
1	1	D3537-7	WEARPAD
1	1	D3553-1	GASKET
1	1	D3553-3	GASKET
18	14	NAS1330S3KB366	INSERT (OR AES10KB366)
4	2	NAS1330S3KB316	INSERT (OR NAS1330C3KB316)
8	6	NAS1330S3KB266	INSERT (OR NAS1330C3KB266)
4	4	NAS1330S3KB216	INSERT (OR NAS1330C3KB216)
16	12	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)
4	4	NAS1330S4KB151	INSERT (OR NAS1330C4KB151)
6	6	AN3C4A	BOLT
4	4	AN3C5A	BOLT
2	2	NAS1515H3L	WASHER
10	10	AN960C10L	WASHER

NO 31858
WORK ORDER
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
ENGINEERING
SECTION CC-CC
(SCALE 1:3)

DRILL 'Q' (Ø0.332-Ø0.338)
C'SINK (Ø0.529X100")
NAS1330S4KB151 INSERT (1)
(4 PLACES)



AN3C4A BOLT (1)
NAS1515H3L WASHER (1)
AN960C10L WASHER (1)
(2 PLACES)
DETAIL T
(SCALE 1:3)
D2646 AFT CAP
SEAL WITH
SIKAFLEX-241/-291

C'SINK AND INSTALL NAS1330S3KBXXX IN HOLES MARKED CS1-CS6 AS FOLLOWS

HOLES MARKED	QTY D3391-015	QTY D3391-025	C'SINK	P/N
CS1	18	14	Ø0.425	NAS1330S3KB366
CS2	4		Ø0.391	NAS1330S3KB366
CS3	4	2	Ø0.391	NAS1330S3KB316
CS4	8	6	Ø0.391	NAS1330S3KB266
CS5	4		Ø0.391	NAS1330S3KB216
CS6	16	12	Ø0.391	NAS1330S3KB166

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

DESIGN PH	DRAWN BY BL	DART DART AEROSPACE USA, INC. PORT HADLOCK, MA	REV. F
CHECKED H	APPROVED H	DRAWING NO. D3391	SHEET 5 OF 5
DATE 07.01.18	TITLE 412 FLOAT SKIDTUBE	SCALE 1:12	

RELEASED
07.03.13 RH
per EEN #934

